



FIG_35: Undrained Shear Strengths from Vane Shear Tests DTX Alignment Along Townsend Street