



FIG\_36: Undrained Shear Strengths from Vane Shear Tests Islais Creek Area Along Davidson Street