



FIG\_47: Correlation of Undrained Strengths from CPT and Vane Shear Tests Mission Bay Site Along Townsend Street