



FIG_54: Undrained Shear Strengths from In-Situ Vane Shear and UU Laboratory Tests Muni Metro Turnback Site