



FIG_110: Stress History and Undrained Shear Strength Profiles for OBC: Mission Bay Area - Townsend Street