



FIG_111: Stress History and Undrained Shear Strength Profiles for OBC: Transbay Terminal and Vicinity