



FIG_135: Normalized Stress-Strain Data from Triaxial Compression Tests on Mélange Matrix Downtown Site – Rincon Hill