



FIG_231 : Lateral Deformations Caused by Jet Grouting
 W:\Infrastructure\Geotech\UC Berkeley 2008 Seminar\Final Figures\11 EXCAVATION\FIG_231.ai