

EXCESS PORE PRESSURES MEASURED AT P-5 DURING JET-GROUTING OF ADJACENT COLUMNS