



Symbol	Test Type
■	Hand Penetrometer Test
●	Torvane at GB-5
▲	Torvane at GB-6
●	Torvane GB-1 to GB-4

Plate K-02: Undrained Shear Strengths from Torvane and hand Penetrometer Tests