



FIG_46: Correlation of Undrained Strengths from CPT and Vane Shear Tests Hamilton Field Site