


Berti, Singh, and Chia (1995)



FIG\_249: Bay Mud Strengths and Excavation Deformations: Rankin Pump Station