



Deflection Behind North Wall



Deflection Behind South Wall



FIG_237: Lateral Deflections Versus Excavation Depth: Overflow Structure Along Islais Creek