


Perpendicular Direction

SUBSURFACE PROFILE

Parallel Direction



Base-Line Reading 06/09/95, After Start of Excavation

**LATERAL DEFORMATIONS MEASURED WITH INCLINOMETER I-8, IN THE AREA BETWEEN MARIN AND ARMY STREETS**