



Plate F-01: Figure A: Typical Measured Lateral Movements for Deepening Excavation on Davidson Avenue-Inclinator No. 7
 Figure B: Maximum Measured Lateral Movements in All Inclinator Nos. Except Nos. 3 and 4